

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-005747**Date Inspected:** 14-Mar-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 1830**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 630**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Chen Likun & Li Ming**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Assembly, Tower**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector Joe Alaniz was present during the times noted above for observations relative to the work being performed.

This QA inspector performed VT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. The member(s) is/are identified as Lift 1 East Tower. The weld designations reviewed are as follows:

Bay 11

ESD1-A165H/J:

111-116, 100, 101, 103-106, 98, 99, 193, 195-205, 209

ESD1-A165F/J:

202-214, 216, 222, 225-228, 233, 234, 236-242

Bay 11

This QA Inspector observed the following work in progress:

ZPMC's qualified welding personnel's identified as Mr. Zhang Liang (067036) and Mr. Chen Dighang (067138) perform FCAW welding on weld joint identified as SD1-A20A/B-15 and 16. ZPMC QC identified Mr. You Qi

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Guo was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2232-TC-5P-F.

Bay 13

ZPMC's qualified welding personnel are identified as Mr. Wang Quanlin (067610) and Mr. Hao Jianxiang (067665) performed SMAW welding on weld joint identified as SSD44-PP11.5-127 and SSD44-PP12.5-127. ZPMC QC identified Mr. Shen Fu You and was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2214.

ZPMC qualified welding personnel identified as Mr. Zhu Ze Zhou (067888) performed FCAW welding on weld joint identified as SP194-001-027. ZPMC QC identified Mr. Shen Fu You and was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2233.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (134-8257-0045), who represents the Office of Structural Materials for your project.

Inspected By:	Alaniz,Joe	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
